Dart Aerospace Ltd. Thursday, 16/08/2007 11:32:44 AM Date User Linda Lacelle **Process Sheet** : STEP WELDMEI : CU-DAR001 Dart Helicopters Services **Drawing Name** Customer Jot Number : 34027 **Estimate Number** : 12577 A/4: : D3562042 **Part Number** P.C. Number S.O. No. : MA : D3562 UNDER REVIEW : 16/08/2007 This Issue **Drawing Number** : N/A Prsht Rev. **Project Number** Type : LARGE FAB ASSY First Issue **Drawing Revision** : 33580 Material Previous Run Each Qty: **Due Date** Written By Checked & Approved By New Issue 06-11-09 JLM Comment Additional Product Jot Number: **Machine Or Operation:** Description: Seq. #: 1.0 D2622120C Extrusion Comment: Qty.: 1.0000 Each(s)/Unit Total: 5.0000 Each(s) Qty Part # Description 334066 D2622-120C Extrusion Check Material for any Dents or Defects 2.0 D2734 206 Step Endplate Comment: Qty.: 2.0000 Each(s)/Unit Total: 10.0000 Each(s) Pick: Description Batch End Cap 334485 **Qtv Part Number** 2 D2734 3.0 LARGE FAB 1 LARGE FABRICATION RESOURCE 1 Comment: LARGE FABRICATION RESOURCE 1


07.10.04 1-Cut D2622 extrusion as per Dwg D3562

07.10.04 2-Deburr and bevel ends for welding $\ \ \mathcal{Q}\cdot \mathcal{N}$

3-Weld (1)end cap as per Dwg D3562& QSI 004. Inspect for foreign objects as per QSI 0.

Aluminum Rod

4-Grind end cap welds flush as per Dwg D3562



W/O:		WORK ORDER CI	HANGES			-,·· <u>-</u>					
DATE	STEP	PROCEDURE CHANGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector				
				••	F						
							•				

Part No: ______ PAR #: _____ Fault Category: ______ NCR: Yes No DQA: ____ Date: ____

QA: N/C Closed:

Date:

NCR:		W	ORK OR	DER NON-CONFORMANC	E (NCR)			
		Description of NC	Corrective Action Section B			Verification	11	
DATE	STEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Section C	Approval Chief Eng	Approval QC Inspector
		The H						
		·						
				;				
							:	

Date: Thursday, 16/08/2007 11:32:44 AM Us€r: Linda Lacelle **Process Sheet** Customer: CU-DAR001 Dart Helicopters Services **Drawing Name: STEP WELDMENT** Part Number: D3562042 Job Number: 34027 ob Number: Seq. #: Description: **Machine Or Operation:** 4.0 INSPECT WORK TO CURRENT STEP QC5 Comment: INSPECT WORK TO CURRENT STEP 5.0 QC9 VISUAL WELDING INSPECTION Comment: VISUAL WE INSPECTION 6.0 HAND FINISHING HAND FINISHING RESOURCE #1 Comment: HAND FINISHING RESOURCE #1 Chemical Conversion Coat as per QSI 005 4.1 QC3 7.0 POWDER COAT/CHEMICAL CONVERSION 8.0 D3560042 Comment: Qtv.: 5.0000 Each(s) 1.0000 Each(s)/Unit Total: ARM WELDMENT D3560044 9.0 ARM WELDMENT Comment: Qty.: 1.0000 Each(s)/Unit Total: 5.0000 Each(s) ARM WELDMENT Batch: 834477 10.0 MS20600AD4W5 36.0000 Each(s)/Unit Total: 180.0000 Each(s) Comment: Qty.: **Blind Rivet** batch: *M105125* 11.0 Comment: SMALL & MEDIUM FAB RESOURCE 1

Drill Rivet holes as per dwg D3562.Touch up alodine.

□age 2

a.M 07.10.12 B 12 01.10.12 2

W/O:		WORK ORDER CHANGES									
DATE	STEP	PROCEDURE CHANGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector				
87-10 M		Split who	It	07.10.11	4						
Part No):	PAR #: Fault Category: NO	R: Yes	No DQA	\:	Date:					

QA: N/C Closed: ____ Date: ____

NCR:			WORK ORDE	ER NON-CONFORMANCE	(NCR)			
		Description of NC		Corrective Action Section B		Verification	Annaual	A
DATE	STEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Section C	Approval Chief Eng	Approval QC Inspector
							٠	
		•						
						¥		
							1991	
					,			

Date: Thursday,: 16/08/2007 11:32:44 AM User: Linda Lacelle **Process Sheet** Customer: CU-DAR001 Dart Helicopters Services **Drawing Name: STEP WELDMENT** Job Number: 34027 Part Number: D3562042 ob Number: Seq. #: Description: **Machine Or Operation:** 07,10,10 (3 Rivet legs using Magnabond as per dwg D3562. Ensure to wipe off any exess magnobond of the step Magnabond 6398 A/R 12.0 QC5 Comment: INSPEC LARGE FABRICATION RESOURCE 1 13.0 LARGE FAB ABRICATION RESOURCE 1 1-Weld Remaining end cap as per Dwg D3562& QSI 004. Inspect for foreign objects as per QSI 024 Aluminum Rod M103794 2-Grind end cap welds flush as per Dwg D3562 14.0 QC9 Comment: VISUAL WELDING INSPECTION 15.0 QC5 INSPECT WORK TO CURRENT STEP WORK TO CURRENT STEP 16.0 POWDER COATING 105068 Comment: POWDER COATING Powder Coat White Gloss (Ref: 4.3.5.1) as per QSI 005 4.3 HAND FINISHING RESOURCE #1 17.0 HAND FINISHING1 Comment: HAND FINISHING RESOURCE #1 Wing Walk as per Dwg D3562 and QSI 005 4.4 Batch: 105694

W/O:		WORK ORDER CHANGES				· - ·, · · · · · · · · · · · · · · · · · ·	
DATE	STEP	PROCEDURE CHANGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
07.10,	担181	Put bushing 02808 # 032896 on Sleps	MF.	07-10- 24.	5	ŧ	
A(w(24	赵	ingroud acts		Alulzy	5		Co Halzy

Part No:	PAR #:	_ Fault Category:	NCR: Yes NO DQA:	Date: MIND
			QA: N/C Closed:	Date:

NCR:		W	ORK OR	DER NON-CONFORMANCE	(NCR)			
DATE	STEP	Description of NC Section A	Initial Chief Eng	Corrective Action Section B Action Description Chief Eng	Sign &	Verification Section C	Approval Chief End	Approval QC Inspector
colodis	华	Derry inspection A forsin object was bend in the self After the CARS were welded. RC. Humman error		Cap to remain form doself, cap to remain form doself, clear and Remore debris Re well hale us per as Too of Re inspect benefacts	Ol.	- Ostevlib	Sour	Shedis Shedis

Dat ::

Thursday, 16/08/2007 11:32:44 AM

User:

Linda Lacelle

Process Sheet

Customer: CU-DAR001 Dart Helicopters Services

Drawing Name: STEP WELDMENT

Job Number: 34027

Part Number: D3562042

cob Number:



Seq. #:

Machine Or Operation:

Description:

18.0

INSPECT POWDER COAT/CHEMICAL CONVERSION



POWDER COAT/CHEMICAL CONVERSION Comment: INSPECT

PACKAGING RESOURCE #1



17-10-2

19.0



Comment: PACKAGING RESOURCE #1

Pick Assembly Kit



20.0



Comment: FINAL INSPECTION/W/O RELEASE



Job Completion



U St. (0.2)

W/O:		WORK ORDER CHANG	SES										
DATE	STEP	PROCEDURE CHANGE		Ву	Date	Qty Appro	Approval Chief Eng / Prod Mgr	Approval QC Inspector					
			7.	e									
		* ;					.∓₃						
Dard Ma							1	1.,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,					

Part No:	PAR #:	Fault Category:	NCR: Yes N	o DQA:	Date: _	
			QA: N/	Closed:	Date: _	11-1

NCR:		W	WORK ORDER NON-CONFORMANCE (NCR)					, +	
		Description of NC		Corrective Action Section B		Verification	Approval	Approval	
DATE	STEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Section C	Chief Eng	Approval QC Inspecto	
				. 4.					
							i		
							<u>.</u>		
	·								
							į.		

